


















**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	
Project Location:		2795 SW 37th Avenue, Miami		Date Completed:		12/18/2013	
Drilling Method:		Hollow Stem Auger		Drilling Contractor:		Enviro Drill, Inc.	
Logged By:		RL		Boring Depth: 5'		Groundwater Level: 4'6"	
Boring ID: SB-4A							
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Surface pavement and limerock	Asphalt (0"-4") with limerock base (4"-6")				
1.0		Limestone	Native limestone (white); No visible solid waste				
1.5							
2.0							
2.5							
3.0							
3.5							
4.0							
4.5							
5.0							
5.5							
6.0							
6.5							
7.0							
7.5							
8.0							
8.5							
9.0							
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							




**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	
Project Location:		2795 SW 37th Avenue, Miami		Date Completed:		12/18/2013	
Drilling Method:		Hollow Stem Auger		Drilling Contractor:		Enviro Drill, Inc.	
Logged By:		RL		Sampling Method:		Split Spoon Sampler	
		Boring Depth: 11'		Groundwater Level: 8'		Boring ID: SB-4B	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Soil	Soil with grass and roots; No visible solid waste				
1.0		Limerock	Limerock; No visible solid waste				
1.5		Limestone	Native limestone (white); No visible solid waste				
2.0							
2.5							
3.0							
3.5							
4.0							
4.5							
5.0							
5.5							
6.0							
6.5							
7.0							
7.5							
8.0							
8.5							
9.0							
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							







**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	Date Completed:
Project Location:		2795 SW 37th Avenue, Miami		Drilling Contractor:		Enviro Drill, Inc.	
Drilling Method:		Hollow Stem Auger		Sampling Method:		Split Spoon Sampler	
Logged By:		RL	Boring Depth: 8'	Groundwater Level: 5'		Boring ID: SB-5	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT		ADDITIONAL DESCRIPTION/COMMENTS			
0.5		Soil		Soil with grass and roots; No visible solid waste			
1.0		Limerock		Limerock; No visible solid waste			
1.5							
2.0							
2.5							
3.0		Limestone		Native limestone (white); No visible solid waste			
3.5							
4.0							
4.5							
5.0							
5.5							
6.0							
6.5							
7.0							
7.5							
8.0							
8.5							
9.0							
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							

**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	Date Completed:
Project Location:		2795 SW 37th Avenue, Miami		Drilling Contractor:		Enviro Drill, Inc.	
Drilling Method:		Hollow Stem Auger		Sampling Method:		Split Spoon Sampler	
Logged By:		RL	Boring Depth: 8'	Groundwater Level: N/A		Boring ID: SB-6	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Soil	Soil with grass and roots; No visible solid waste				
1.0		Limerock	Limerock; No visible solid waste				
1.5							
2.0							
2.5							
3.0		Limestone	Sand fill unit; No visible solid waste				
3.5							
4.0							
4.5							
5.0							
5.5							
6.0							
6.5							
7.0							
7.5							
8.0							
8.5							
9.0							
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							

**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	Date Completed:
Project Location:		2795 SW 37th Avenue, Miami		Drilling Contractor:		Enviro Drill, Inc.	
Drilling Method:		Hollow Stem Auger		Sampling Method:		Split Spoon Sampler	
Logged By:		RL	Boring Depth: 12'	Groundwater Level: 8'6"		Boring ID: SB-7	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Soil	Top soil mixed with glass fragments				
1.0		Limerock	Limerock mixed with glass fragments				
1.5		Land Fill Material (approx. 60%)	Fine black matrix (possible incinerator residue) mixed with charred rubber, wood, metal, and glass fragments				
2.0							
2.5							
3.0							
3.5							
4.0							
4.5							
5.0							
5.5							
6.0							
6.5		Limestone	Native limestone; stained gray				
7.0			Native limestone (white); No visible solid waste				
7.5							
8.0							
8.5							
9.0							
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							





**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	
Project Location:		2795 SW 37th Avenue, Miami		Date Completed:		12/18/2013	
Drilling Method:		Hollow Stem Auger		Drilling Contractor:		Enviro Drill, Inc.	
Logged By:		RL		Sampling Method:		Split Spoon Sampler	
		Boring Depth: 12'		Groundwater Level: 9'		Boring ID: SB-8A	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Soil	Soil with grass and roots; No visible solid waste				
1.0			Soil, glass fragments, and a fine black material (possible incinerator residue)				
1.5							
2.0		Land Fill Material (approx. 70%)	Limerock, sand, soil, glass fragments, and a fine black material (possible incinerator residue)				
2.5							
3.0							
3.5			Limerock, glass fragments, and a fine black material (possible incinerator residue)				
4.0							
4.5							
5.0							
5.5							
6.0							
6.5			Fine black matrix (possible incinerator residue) mixed with charred wood, metal, and glass fragments				
7.0							
7.5							
8.0							
8.5							
9.0							
9.5		Limestone	Native limestone (white); No visible solid waste				
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							

**Douglas Park Investigation  
Soil Boring Log**




Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/18/2013	
Project Location:		2795 SW 37th Avenue, Miami		Date Completed:		12/18/2013	
Drilling Method:		Hollow Stem Auger		Drilling Contractor:		Enviro Drill, Inc.	
Logged By:		RL		Sampling Method:		Split Spoon Sampler	
		Boring Depth: 13'		Groundwater Level: 11'		Boring ID: SB-8B	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Soil	Soil with grass and roots; No visible solid waste				
1.0		Limerock	Limerock mixed with glass fragments				
1.5		Land Fill Material (approx. 50%)	Fine black matrix (possible incinerator residue) mixed with glass				
2.0			Limerock, sand, soil, glass fragments, and a fine black material (possible incinerator residue)				
2.5							
3.0							
3.5							
4.0							
4.5							
5.0							
5.5							
6.0							
6.5	Charred wood, metal, and glass fragments in a fine black matrix (possible incinerator residue) mixed with						
7.0							
7.5							
8.0							
8.5							
9.0	Native limestone (white); No visible solid waste						
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							

**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:	12/18/2013	Date Completed:	12/18/2013
Project Location:				2795 SW 37th Avenue, Miami		Drilling Contractor:	
Drilling Method:				Hollow Stem Auger		Enviro Drill, Inc.	
Logged By:				RL		Boring Depth: 11'6"	
Groundwater Level: 10'				Boring ID: SB-9			
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5 1.0		Soil	Soil with grass and roots; No visible solid waste				
1.5 2.0 2.5 3.0 3.5 4.0 4.5 5.0 5.5 6.0 6.5 7.0 7.5 8.0 8.5 9.0		Limerock	Limerock in a fine black matrix (possible incinerator residue) mixed with charred, wood, metal, and glass fragments				
			Mixed sand fill unit with glass fragments				
			Limerock; No visible solid waste				
			Limerock with a fine black matrix (possible incinerator residue) mixed with charred, wood, metal, and glass fragments				
9.5		Land Fill Material (approx. 60%)	Brown clay mixed with black unrecognizable charred material				
10.0 10.5 11.0 11.5		Limestone	Native limestone (white); No visible solid waste				
12.0 12.5 13.0 13.5 14.0 14.5 15.0							



**Douglas Park Investigation  
Soil Boring Log**

Client:		City of Miami		Project Name:		Douglas Park Investigation	
Project Number:		12639984		Date Started:		12/19/2013	Date Completed:
Project Location:		2795 SW 37th Avenue, Miami		Drilling Contractor:		Enviro Drill, Inc.	
Drilling Method:		Hollow Stem Auger		Sampling Method:		Split Spoon Sampler	
Logged By:		PT	Boring Depth: 8'	Groundwater Level: N/A		Boring ID: SB-10	
Depth (ft)	GRAPHIC LOG	MAIN SOIL COMPONENT	ADDITIONAL DESCRIPTION/COMMENTS				
0.5		Surface pavement and limerock	Asphalt (0"-1.5") with limerock base (1.5"-6")				
1.0		Limerock	Limerock; No visible solid waste				
1.5			Limerock (gray) mixed with glass fragments (12" - 14")				
2.0			Limerock; No visible solid waste				
2.5							
3.0							
3.5							
4.0							
4.5							
5.0							
5.5							
6.0	Native limestone (yellow/white); No visible solid waste						
6.5							
7.0							
7.5							
8.0							
8.5							
9.0							
9.5							
10.0							
10.5							
11.0							
11.5							
12.0							
12.5							
13.0							
13.5							
14.0							
14.5							
15.0							